\$160,000



























Listing

Listing url: https://aircraftforsale.com//aircraft/single-engine-piston/piper/pa-28r-201t-turbo-arrow-iii-for-arrow-iii/spanish-fork-ut-84660-usa/piper-pa-28r-201t-turbo-arrow-iii-for-sale-500605

Listing reference number #500605

Seller

PacTex Aviation

Phone: +1 (817) 454-0690

Quick info

Exterior: Exterior Condition:Factory paint.

Paint Condition Score: 5Paint Year: 1978

Listing type: For sale

Description

PacTex Aviation is presenting this 1978 turbo Piper Arrow III! Cruise in the flight levels with N3587M. Perfect candidate to build your dream turbo arrow, or keep it as is and enjoy flying over the weather.

Located in Spanish Fork, Utah.

The fully digitized logs are available on our website HERE in addition to many more photos.

curtains included!

\$160,000

Add Details

Manufacturer year: 1978

Serial number: 28R-7803179

Registration number: N3587M

Total airframe time: 2739

Additional information

Airframe:

Airframe Description:

Only 2739 Hours on the airframe. All logs since new. Annual on 7/19/2024.

Knots 2U Gap Seals

Airframe Total time: 2739
Engine 1 hours: 837 SFOH

Propulsion:

TSIO-360-FB6B

Exhaust overhauled in 2022

Inspection:

Inspection Status:

Annual on 7/19/2024

Damage history:

Gear up 2004

slight hangar rash right wing leading edge.

Avionics:

Flight rules: IFR

Comms equipment:

GMA 340 Audio Panel

GTX 327 Transponder

Engine management:

Navigation equipment:

GNS 430W

Flight Stream 210

CHT/EGT Monitor

Additional equipment:

GDL 88 ADS-B In/Out

\$160,000

Interior:

Number of seats: 4

Interior Condition:

Factory interior.

Interior Year: 1978

Interior Condition Score: 6


\$160,000

Listing images

























\$160,000

MODEL TETE Piper Yarbo Annie S AFTT 2726-27	Senial Number you recen're SMOH 404.4	Amorath location liparesh Fork, chah SPOH 190.6	Surrage history Spar up in 2004	
Avionics	Engine	Upgrades	Inspection	STC
OARS SHE SHEET	Toro and room	Kinin 20 Gap Smith	Annual on 7:79/3004	
DTX 927 Transpositer	Exhaust prechaded in 1855		All tops to the real	
DOLEKADOR NOV			Attitude indicator not working	
ONO REPORT			Promper rack on right along treating order	
Olyke Denson 210			Sactory Panishmener	