











Listing

Listing url: https://aircraftforsale.com//aircraft/multi-engine-piston/cessna/310r/madison-wi-usa/cessna-310r-for-sale-500761

Listing reference number #500761

Seller

leff Baum

Phone: +1 (920) 261-4567

Quick info

Listing type: For sale

Description

Well-taken-care-of C310R, ready to be your next family or business hauler!

Add Details

Manufacturer year: 1975

Serial number: 310R0136

Registration number: N213JD

Total airframe time: 10985

Additional information

Airframe:

Airframe Description:

No Known Damage History

- . .

Complete Logs

Heater Hobbs: 680.0

Heater Overhauled: 388.6

Annual Due: 08/2025

All AD's and mandatory SB's are in compliance

Left Engine Mags Overhauled 8/2024 by Poplar Grove

Alt. Static Transponder Cert. 12/2024

New Gill Battery Installed 3/2023

Airframe Total time: 10985

Total hours flown in the past 6 months: 25

Engine 1 hours: 1080 SMOH
Engine 2 hours: 25 SFRM

Propulsion:

Left Engine: Continental IO-520-M (Overhauled 12/2007 by Poplar Grove Airmotive)

Left Engine SMOH: 1080 Last Compressions 66,56,64,51,56,72

Right Engine: Continental IO-520-MB1B (Factory Remain 08/2024)

Right Engine SFRM: 25

Prop L/R/ SOH: 228/25 (6/2021 & 8/2024 by H&S)

Props: McCauley 3 Blade 3AF32C528

Inspection:

Inspection Status:

Annual due 8/2025

Inspection Expiry: August 31, 2025

Damage history:

No Known Damage History

Avionics:

Flight rules: IFR

Comms equipment:

Garmin 35C Remote Audio Panel

Engine management:

Navigation equipment:

Garmin GI-275 HSI

Garmin GI-275 ADI

Garmin 750XI Com/Nav

Garmin FlightStream 210 (Connext Bluetooth)

Garmin 430W Com/Nav

Garmin GTX345

S-TEC 55X Autopilot

Autopilot annunciation panel

Flight Director

EDM 760

Additional equipment:

Garmin 396 with SiriusXm

Davtron Electronic Clock

Pilot/Co-Pilot Bose Lemmo Plugs

Garmin USB Outlet

Co-Pilot Panel Mounted Ram Mount

GAMI injectors

BLR VG kit

2050 lbs useful load

Interior:

Number of seats: 6

Interior Condition:

7/10 - green, newer carpet

Exterior:

Exterior Condition:

7/10 - paint and boots in fair condition

Paint Condition Score: 7

Listing images











