\$90,000









Listing

Listing url: https://aircraftforsale.com//aircraft/single-engine-piston/stinson/l-5g-sentinel/stockton-ca-usa/stinson-l-5g-sentinel-for-sale-501363

Listing reference number #501363

Seller

Jan Johnson

Phone: +1 (650) 704-8469

Quick info

Exterior: Exterior Condition:Fuselage skin replaced - |

2022All surfaces painted - 2022Paint Condition Score: 9Paint Year: 2022

Listing type: For sale

Aircraft For Sale

Bringing buyer and seller together!

2/5

Stinson L-5G Sentinel

\$90,000

Description

1945 Stinson L-5G Sentinel ambulance, built under contract at the Consolidated Vultee factory in Wayne, Michigan

Immaculate restored condition with low 1,719 hours TT on airframe. 70 hours since complete IRAN on engine and airframe. New fuselage fabric and overall new paint (over \$100,000 spent), Garmin GTR-225 COM and GTX-345 xpdr with ADS-B In/Out. Turnkey warbird, ready for air shows, fly-ins, and fun cross countries.

Great entry-level warbird. Will accept best offer.

Add Details

Manufacturer year: 1945

Serial number: 4646

Registration number: N63355

Total airframe time: 1720

\$90,000

Additional information

Airframe:

Airframe Description:

Airplane completely dismantled in 2021 for IRAN. 70 hours since IRAN.

New fabric on fuselage, and all new paint/livery

Airframe Total time: 1720

Total hours flown in the past 6 months: 25

Engine 1 hours: 70 SFOH

Propulsion:

Lycoming O-435-11 6-cylinder engine, 190 horsepower. Great compression in all six cylinders (April 2024).

Inspection:

Inspection Status:

Current annual inspection April 2024

Inspection Expiry: April 30, 2025

Damage history:

None

Avionics:

Flight rules: VFR

Comms equipment:

Garmin GTR-225 COMM (2018)

Garmin GTX-345 Transponder, ADS-B In/Out

Navigation equipment:

Additional equipment:

Original WW II navigation and comm equipment installed - INOP. For appearance only.

Interior:

Number of seats: 2

Additional equipment: Dual-controls

Interior Condition:

Interior rejuvenated in 2022

Interior Year: 2022

Interior Condition Score: 9

\$90,000

Listing images

























\$90,000





















